



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program August 23, 2012

Reviewed: *PPF*

<b>Mine Name:</b> Solar Wind	<b>Permit Number:</b> S/023/0061
<b>Operator Name:</b> Got Named Inc	<b>Inspection Date:</b> <del>October 26, 2011</del> 8/23/2012
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> August 23, 2012
<b>Other Participants:</b> none	<b>Mine Status:</b> Suspended
<b>Weather Condition:</b> 81 degrees partly cloudy	<b>Last Inspection:</b> October 26, 2011
<b>Bond Renewal Date:</b> April 5, 2014	<b>Bond Amount:</b> \$7,400.00
<b>Surface Ownership:</b> BLM	<b>Mineral Ownership:</b> BLM
<b>Last Year of Production:</b> 2011	<b>Acreage:</b> 1 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This is a routine inspection.

#### Inspection Summary:

The last surety estimate for the Solar Wind Mine was done in 2009 and escalated to 2012 dollars. The surety amount needs to be adjusted to account for changes in reclamation costs.

Based on average reclamation costs, the surety amount needs to be increased from \$7,400.00 to \$7,900.00 for a three (3) year escalation or \$8,100.00 for a five (5) year escalation.

The site has no equipment on site. The site appears to be stable.

**Conclusions and Recommendations:**

The Division should have the bond increase.

**Directions to Site:**

**Inspector's Signature**

WHW:

cc: (OPERATOR)

Jerry Mansfield, BLM

O:\M023-Juab\S0230061-SolarWind\inspections\Insp-08232012.doc

A handwritten signature in dark ink, appearing to read "Wayne W. Wester", is written over a horizontal line.



Access road to the site.



Waste product on site





Highwalls



Pit